

Major Incidents at Nuclear Facilities April 2008 - March 2009

Date	Facility Name	Incident Description
1 April 08*	Shika-2	Reactor shutdown manually due to elevated hydrogen concentration in the off-gas treatment system.
9 April 08	Tomari-2	Cracks found in welds in primary coolant inlet nozzle stubs of steam generators A & B.
18 April 08	Sendai-1	Broken main shaft of charging/high-pressure injection pump A.
12 May 08*	Shika-2	Elevated hydrogen concentration in the off-gas treatment system.
14 May 08	RRP	Exhaust fan stopped in the waste gas treatment system in the high-level liquid waste vitrification building.
25 May 08	Fuku. 1-5	Reactor shutdown manually due to deviation from the limiting condition for operation of the high-pressure core injection system and reactor core isolation cooling system.
26 May 08	Ohi-3	Cracks in the weld of the reactor vessel A-loop outlet nozzle stub.
27 June 08	KK-6	Failure of one control rod drive mechanism to couple with the corresponding control rod.
2 July 08	RRP	Molten glass stopped flowing through the nozzle at the bottom of vitrification furnace A in the high-level liquid waste vitrification building.
9 July 08	GNF Yokosuka	Uranium leaked from a press during the pellet production process in number 2 fabrication building.
18 July 08	Tomari-1	Failure of charging pump motor A during testing.
21 July 08	Tsuruga-2	Failure of a DC motor operated starting steam inlet valve for the turbine driven auxiliary feedwater pump.
23 July 08*	Onagawa-1	Crack in a weld in a recirculation pipe.
3 Aug. 08	Shimane-1	High pressure core injection turbine shut down during testing.
7 Aug. 08	Tokai-2	Valve disc fallen away from a check valve in the steam system exhaust line of the reactor core isolation cooling system turbine.
8 Aug. 08	GNF Yokosuka	Uranium spattered in the uranium recovery room of number 2 fabrication building.
19 Aug. 08*	Ohi-4	Leak from a fuel assembly.
4 Sep. 08	Tomari-1	Significant thinning of one heat exchange tube in steam generator A.
9 Sep. 08	Monju	Hole corroded in the exhaust duct in the roof of the reactor support building.
16 Sep. 08	Tsuruga-2	Reactor shutdown manually due to steam leak from a weld in the high pressure turbine.
22 Sep. 08	Takahama-4	Significant thinning of one heat exchange tube in steam generator C.
3 Oct. 08	Takahama-4	Cracks in welds in all primary coolant inlet nozzle stubs of the 3 steam generators.
5 Nov. 08	Hamaoka-5	Reactor shutdown manually due to rise in temperature in the noble gas holdup equipment of the off-gas treatment system. Hydrogen concentration rose to about 50%. It is suspected that a hydrogen explosion occurred.
7 Nov. 08	Fuku. II-3	During testing of control rod drive mechanism, 1 control rod that was not being tested inserted too far (beyond the fully inserted position).
13 Nov. 08*	Tomari-1	Cracks found in welds in primary coolant inlet nozzle stubs of steam generators A and B.
26 Nov. 08	Fuku. I-1	Water leaked from valves in the control rod drive hydraulic control unit.
10 Dec. 08	RRP	A stirring rod, which had been inserted into vitrification furnace A in the high-level liquid waste vitrification facility, was found to be bent and to have damaged the furnace.

11 Dec. 08	Tsuruga-1	Holes corroded in two places in ducts in the ventilation system of the central control room.
12 Dec. 08*	Sendai-2	Cracks in welds in primary coolant inlet nozzle stubs of steam generators A, B and C.
22 Dec. 08	Hamaoka-3	Emergency diesel generator A damaged during testing. Power decreasing operation became unavailable.
30 Dec. 08	Hamaoka-5	Reactor shutdown manually due to elevated hydrogen concentration in the off-gas treatment system.
25 Feb. 09	Fuku. I-1	During reactor startup, a drive bolt was broken in the turbine bypass valve. The valve was fully closed, so reactor pressure increased. Reactor power was decreased manually.
23 Mar. 09	Onagawa-1	One control rod that was not being operated accidentally inserted from the fully withdrawn to the fully inserted position.
26 Mar. 09	Shimane-1	During a half scram test during normal operation, 1 control rod accidentally inserted from the fully withdrawn to the fully inserted position.
26 Mar. 09	Fuku. I-3	During testing of control rod drive hydraulic system, 1 control rod inserted too far (beyond the fully inserted position).

* Reporting not legally required. In all other cases listed reporting was required under the Law for the Regulation of Nuclear Source Material, Nuclear Fuel Material and Reactors

RRP = Rokkasho Reprocessing Plant; Fuku. = Fukushima; KK = Kashiwazaki-Kariwa; GNF = Global Nuclear Fuel - Japan Co., Ltd.